\$502207 ATTACHMENT -Page 153 of 23

#### SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : ACTIVE THERMAL CONTROL FMEA NO 06-3C -0304 -1 REV:08/29/:

ASSEMBLY : FREON THERMAL LOOP

CRIT. FUNC:

P/N RI 1MC250-0001-0025 CRIT. HOW:

P/N VENDOR:SV755511

102 103 104 X X

LIV IU

YTITKAUD :1

EFFECTIVITY:

:ONE/VEHICLE

PHASE (5): PL LO X OO X DO X LS

PREPARED BY:

REDUNDANCY SCREEN: A-PASS B-PASS C-PAS.

DES

APPROVED BE: O. TRANSA/ DES

APPROVED\_BY\_ (NASA) -SSM

REL

D. RISING & REL

REL

QE

W. SMITH PASOE

VEHICLE

ITEM:

HEAT EXCHANGER, GSE.

### FUNCTION:

THE GSE HEAT EXCHANGER TRANSFERS ORBITER WASTE HEAT VIA PREON COOLANT LOOPS TO GROUND SUPPORT EQUIPMENT DURING GROUND TURNAROUND. THE HEAT EXCHANGER WAS DESIGNED WITH REDUNDANT GSE LOOPS. THE REDUNDANT GSE LOC IS CAPPED AND NOT IN USE.

#### FAILURE MODE:

INTERNAL LEAKAGE, FREON 21 TO FREON 21.

## CAUSE(S):

VIBRATION, MECHANICAL SHOCK, CORROSION.

# EFFECT(S) ON:

- (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VENICLE
- (A) THE TWO FRECH COOLANT LOOPS BECOME INTERCONNECTED RESULTING IN TRANSFER OF COOLANT FROM ONE LOOP TO THE OTHER UNTIL PRESSURE IN BOTH LOOPS IS EQUALIZED.
- (B) NO EFFECT.
- (C) POSSIBLE LOSS OF MISSION. EARLY MISSION TERMINATION FOR FIRST FAILURE.
- (D) SECOND ASSOCIATED FAILURE (EXTERNAL LEAKAGE OF ONE FREON COOLANT LOOP) WILL CAUSE LOSS OF ALL VEHICLE COOLING AND MAY RESULT IN LOSS OF CREW/VERICLE.

#### SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : ACTIVE THERMAL CONTROL FMEA NO 06-3 -0304 -1 REV:08/29/88

#### DISPOSITION & RATIONALE:

(A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE RISTORY (2) OPERATIONAL USE

# (A) DESIGN

THE HEAT EXCHANGER IS MADE FROM STAINLESS STEEL AND NICKEL BRONZE ALLOYS, WHICH ARE CORROSION RESISTANT AND COMPATIBLE WITH FREON 21 AND FREON 114, AND CONTAINS NO MOVING PARTS SUBJECT TO WEAR. THE FLOW HEADERS ARE MACHINED FROM A SINGLE PIECE STAINLESS STEEL BAR. THE HEADERS ARE WELDED TO THE CORE, WHICH IS MADE OF STACKED PLATE-FIN PARTING SHEETS (THICKNESS = 0.005 INCH). DESIGN PROOF PRESSURE IS 1.5 AND BURST PRESSURE IS 2.0 TIMES MAXIMUM OPERATING PRESSURE.

#### (B) TEST

QUALIFICATION TEST - QUALIFICATION TESTED FOR 100 MISSION LIFE. THE MEDICHANGER WAS SUBJECTED TO A PROOF/RUPTURE TEST FOR QUALIFICATION.

DESIGN PROOF IS 575 PSIG AND UNIT DID NOT RUPTURE UNTIL 2440 PSIG (MAXIMUM GSE FREON 114 OPERATING PRESSURE IS 250 PSIA). VIBRATION TESTED AT 0.075 G<sup>2</sup>/HZ FOR 52 MIN/AXIS, SHOCK TESTED AT +/- 20 G EACH AXIS:

ACCEPTANCE TEST - CLOSURE BAR AND CORE STACK IS LEAK TESTED BEFORE HEAD: ASSEMBLY IS WELDED. HEAT EXCHANGER ASSEMBLY IS LEAK TESTED DURING ACCEPTANCE TESTING TO VERIFY INTEGRITY OF COMPLETE COMPONENT.

OMRSD - FCL'S ARE LEAK CHECKED PRIOR TO EACH FLIGHT. FLUID USZ CONTROLLED TO SE-S-0071.

# (C) INSPECTION

# RECEIVING INSPECTION

RAW MATERIAL AND PURCHASED COMPONENTS REQUIREMENTS ARE VERIFIED BY INSPECTION. PARTS PROTECTION IS VERIFIED BY INSPECTION.

## CONTABLUATION CONTROL

SYSTEMS FIUID ANALYSES FOR CONTAMINATION ARE VERIFIED BY INSPECTION. CONTAMINATION CONTAMINATION CONTAMINATION CONTAMINATION CONTROL PROCESSES AND CLEAN AREAS ARE VERIFIED BY INSPECTION.

# ASSEMBLY/INSTALLATION

MANUFACTURING, INSTALLATION, AND ASSEMBLY OPERATIONS ARE VERIFIED BY INSPECTION. SHEET METAL PARTS ARE INSPECTED AND VERIFIED BY INSPECTION. SURFACE FINISHES VERIFIED BY INSPECTION. DIMENSIONS VERIFIED BY INSPECTION.

## CRITICAL PROCESSES

WELDING IS VERIFIED BY INSPECTION. ALL WELDS ARE STRESS RELIEVED AFTER WELDING, VERIFIED BY INSPECTION. BRAZING IS VERIFIED BY INSPECTION.

### NONDESTRUCTIVE EVALUATION

HEADER WELDS TO THE TUBES ARE PENETRANT AND X-RAY INSPECTED. OTHER WELDS (MOUNTING PADS AND HEADER WELDS TO THE CORES) ARE PENETRANT AND 10X MAGNIFICATION VISUALLY INSPECTED. BRAZES ARE VERIFIED BY PROOF AND LEAK TESTS.

## SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : ACTIVE THERMAL CONTROL FMEA NO 06-3 -0304 -1 REV:08/29/85

TESTING

INSPECTION VERIFIES THAT RESULTS OF ACCEPTANCE TESTING AND FLOWRATES ARE WITHIN SPECIFIED LIMITS.

HANDLING/PACKAGING HANDLING AND PACKAGING REQUIREMENTS VERIFIED BY INSPECTION.

- (D) FAILURE HISTORY NO FAILURE HISTORY.
- (E) OPERATIONAL USE GROUND CONTROLLER WILL IDENTIFY HARDWARE FAILURE. FUND IN PRESSURES CONVERGE AND ACCUMULATOR QUANTITIES DIVERGE. BOTH LOOPS WILL OPERATE MORMALLY. A LEAK IN EITHER LOOP WILL CAUSE LOSS OF BOTH LOOPS, THEREFORE, THIS PAILURE IS TREATED AS A LOSS OF ONE FREON LOOP. NEXT PRIMARY LANDING SITE.